



4X4 ENGINEERING



Technical Bulletin: 70 Series 1VD-FTV

Please read before proceeding with fitment

Please ensure that the Diesel Particulate Filter (DPF) temperature sensor connectors are plugged into the correct mating connectors on the gearbox wiring harness.

Temp sensor 1 - Grey connector to Grey Connector

Temp sensor 2 - Black Connector to Black connector

If these connectors are fitted incorrectly it will lead to DPF blockages and DPF failure.

For any further information please contact Safari 4x4 Engineering on (03) 9761 7244 or E-mail support@safari4x4.com.au

